

DATE	DESCRIPTION	HOUR METER
11/14/2015	Oil change	
11/18/2015	Transmission oil change	
11/19/2015	Raw water, sink drain, head x 3 through hulls exercised.	
3/14/2016	Haulout at Seaview North	
4/26/2016	Raw water, sink drain, head x 3 through hulls exercised.	
4/26/2016	Rebed chain plate covers, diesel fill	
4/27/2016	Change motor oil, oil filter, transmission oil. Check pencil zinc. Oil & ATF analysis	
4/27/2016	Inspect fire extinguishers	
4/30/2016	Replace water pump impeller.	
4/30/2016	Raw water, sink drain, head x 3 through hulls exercised.	
5/15/2016	Raw water, sink drain, head x 3 through hulls exercised.	
6/28/2016	Raw water, sink drain, head x 3 through hulls exercised.	
6/28/2016	Propane system tested for leaks.	
7/3/2016	Raw water, sink drain, head x 3 through hulls exercised.	
9/17/2016	Bottom scrubbed by Sound Divers	
9/24/2016	Raw water, sink drain, head x 3 through hulls exercised.	
10/12/2016	Change motor oil, oil filter, transmission oil. Check pencil zinc. Oil & ATF analysis	
10/12/2016	Headsail removed for winter.	
10/13/2016	Head flushed with vinegar, flushed with fresh water.	
10/14/2016	Raw water, sink drain, head x 3 through hulls exercised.	
3/9/2017	Raw water, sink drain, head x 3 through hulls exercised. Check pencil zinc.	
3/10/2017	Change motor oil, oil filter, transmission oil.	
3/11/2017	Clean and dry bilge. Replace bilge pump switch.	
3/14/2017	Raw water, sink drain, head x 3 through hulls exercised.	
4/14/2017	Raw water, sink drain, head x 3 through hulls exercised.	
4/18/2017	Replace fresh water engine hoses x 2	
4/18/2017	Flush raw water system with fresh water.	
4/19/2017	Raw water, sink drain, head x 3 through hulls exercised.	
6/1/2017	Diver: hull cleaned, rudder foot zinc "wasted", shaft zinc half gone, replaced.	
6/19/2017	Raw water, sink drain, head x 3 through hulls exercised.	
7/1/2017	Raw water, sink drain, head x 3 through hulls exercised. Manifold exercised.	
9/24/2017	Raw water, sink drain, head x 3 through hulls exercised. Manifold exercised.	
9/24/2017	Replace heat exchanger zinc	
9/26/2017	Diver: clean hull, both zincs look good.	
10/14/2017	Change motor oil, oil filter, transmission oil. Oil samples taken.	58.0
10/15/2017	Vacuum dry bilge, replace pads with oil boom.	
10/15/2017	Raw water system flushed with fresh water for storage.	
10/15/2017	Raw water, sink drain, head x 3 through hulls exercised. Manifold exercised.	
11/1/2017	Headsail: luff repaired, new sacrificial leech cover with new stitching.	
3/9/2018	Raw water, sink drain, head x 3 through hulls exercised. Manifold exercised.	58.1
3/12/2018	Raw water system flushed with fresh water for storage.	
3/12/2018	Raw water, sink drain, head x 3 through hulls exercised. Manifold exercised.	
4/3/2018	Haul out	

4/6/2018	Sand hull. Ablative Seahawk Cukote paint (one coat) applied.	
4/10/2018	Raw water, sink drain, head x 3 through hulls exercised. Manifold exercised.	
4/10/2018	Sea valves lubed.	
4/10/2018	Propeller polished.	
4/10/2018	Shaft and rudder foot zincs changed.	
4/11/2018	Diesel deck fill gasket replaced.	
4/11/2018	Mast winches, main sheet winch serviced (cleaned & lubed)	
4/12/2018	Raw water impeller and gasket changed.	64.8
4/12/2018	Oil change, transmission oil change.	64.8
4/12/2018	Raw water system flushed with fresh water for storage.	
6/24/2018	Raw water, sink drain, head x 3 through hulls exercised. Manifold exercised.	
6/24/2018	Raw water system flushed with fresh water for storage.	
8/4/2018	Paint cove strip, paint pilothouse top stripe	
8/5/2018	Climb mast, inspect rigging, tighten starboard spreader bolt.	
8/5/2018	Lube steering system (under cockpit)	
8/6/2018	Raw water, sink drain, head x 3 through hulls exercised. Manifold exercised.	
8/6/2018	Fill propane (1.75 gallons). Leak test propane system.	
9/15/2018	Raw water, sink drain, head x 3 through hulls exercised. Manifold exercised.	
10/5/2018	Oil, oil filter, transmission oil changed.	105.7
10/6/2018	Raw water system flushed with fresh water and salt away for storage	
10/7/2018	Raw water, sink drain, head x 3 through hulls exercised. Manifold exercised.	
3/7/2019	Raw water, sink drain, head x 3 through hulls exercised. Manifold exercised.	
3/10/2019	Raw water system flushed with fresh water and salt away for storage	
3/11/2019	Raw water, sink drain, head x 3 through hulls exercised. Manifold exercised.	
4/22/2019	Raw water, sink drain, head x 3 through hulls exercised. Manifold exercised.	
4/26/2019	Raw water system flushed with fresh water and salt away for storage	
4/26/2019	Raw water, sink drain, head x 3 through hulls exercised. Manifold exercised.	
4/26/2019	Bilge shop vac'ed dry	
5/19/2019	Raw water, sink drain, head x 3 through hulls exercised. Manifold exercised.	
6/1/2019	Raw water system flushed with fresh water and salt away for storage	
6/1/2019	Raw water, sink drain, head x 3 through hulls exercised. Manifold exercised.	
6/1/2019	Bilge shop vac'ed dry	
9/6/2019	Raw water, sink drain, head x 3 through hulls exercised. Manifold exercised.	
9/15/2019	Replace fuse holder on solenoid exciter wire.	
9/26/2019	Remove headsail for winter	
9/26/2019	Raw water system flushed with fresh water and salt away for storage	
9/26/2019	Raw water, sink drain, head x 3 through hulls exercised. Manifold exercised.	
9/26/2019	Bilge shop vac'ed dry	
9/26/2019	Oil, oil filter, transmission oil changed.	127.2
6/19/2020	Raw water, sink drain, head x 3 through hulls exercised. Manifold exercised.	
6/30/2020	Attach headsail for summer	
7/2/2020	Raw water system flushed with fresh water and salt away for storage	
7/2/2020	Raw water, sink drain, head x 3 through hulls exercised. Manifold exercised.	
7/2/2020	Bilge shop vac'ed dry	
10/4/2020	Raw water, sink drain, head x 3 through hulls exercised. Manifold exercised.	
1/8/2021	Raw water, sink drain, head x 3 through hulls exercised. Manifold exercised.	
1/8/2021	Bilge shop vac'ed dry	

4/8/2021	Raw water, sink drain, head x 3 through hulls exercised. Manifold exercised.	
4/19/2021	Raw water, sink drain, head x 3 through hulls exercised. Manifold exercised.	
6/7/2021	Raw water, sink drain, head x 3 through hulls exercised. Manifold exercised.	
6/8/2021	Engine oil & oil filter change, transmission oil change	138.4
6/8/2021	Replace stern navigation light	
6/8/2021	Port upper shroud clevis pin replaced	
6/8/2021	Rebed all port chainplates, rear starboard chain plate.	
6/9/2021	Secure Wallas exhaust in rear locker	
6/9/2021	Forward engine bracket wire brushed and painted	
6/9/2021	Replace fire extinguisher	
6/9/2021	Top off batteries.	
6/9/2021	Trim battery interconnects, re route, max 4 rings per terminal	
6/9/2021	Alternator / water pump belt replaced	
6/10/2021	Flush raw water system with Salt Away and fresh water	
6/10/2021	Shop vac bilge dry	
6/10/2021	Raw water, sink drain, head x 3 through hulls exercised. Manifold exercised.	
7/10/2021	Raw water, sink drain, head x 3 through hulls exercised. Manifold exercised.	
8/31/2021	New PSS dripless shaft seal, new cutlass bearing	
9/5/2021	Raw water, sink drain, head x 3 through hulls exercised. Manifold exercised.	
9/10/2021	Flush raw water system with Salt Away and fresh water	
5/14/2022	Raw water, sink drain, head x 3 through hulls exercised. Manifold exercised.	
5/28/2022	Raw water, sink drain, head x 3 through hulls exercised. Manifold exercised.	149.7
9/25/2022	Raw water, sink drain, head x 3 through hulls exercised. Manifold exercised.	
10/8/2022	Raw water, sink drain, head x 3 through hulls exercised. Manifold exercised.	
4/28/2023	Raw water, sink drain, head x 3 through hulls exercised. Manifold exercised.	
7/24/2023	Raw water, sink drain, head x 3 through hulls exercised. Manifold exercised.	
9/28/2023	Raw water, sink drain, head x 3 through hulls exercised. Manifold exercised.	
10/7/2023	Oil change. Oil filter change. New bilge sock (boom).	170.1
10/7/2023	Flush raw water system with Salt Away and fresh water	
10/7/2023	Raw water, sink drain, head x 3 through hulls exercised. Manifold exercised.	
4/15/2024	Raw water, sink drain, head x 3 through hulls exercised. Manifold exercised.	
6/1/2024	Change Wallas fuel line to USCG approved	
6/1/2024	Rebed all shrouds	
6/1/2024	Inspect heat exchanger, inspect exhaust system	
6/1/2024	Replace raw water impeller, bearing, shaft.	
6/1/2024	2 coats Seahawk Cukote bottom paint	
6/1/2024	Scrape and sand prior to painting	
6/1/2024	Replace anodes	
6/1/2024	New diesel primary fuel filter	
6/1/2024	New manual bilge pump with separate hose and separate through hull	
6/13/2024	Raw water, sink drain, head x 3 through hulls exercised. Manifold exercised.	
6/21/2024	Raw water, sink drain, head x 3 through hulls exercised. Manifold exercised.	
6/21/2024	Flush raw water system with Salt Away and fresh water	
6/24/2024	New 12v bilge pump installed and tested	
9/13/2024	Replace cracked exhaust hose	
9/24/2024	Flush raw water system with fresh water	
10/6/2024	Raw water, sink drain, head x 3 through hulls exercised. Manifold exercised.	

4/17/2025 Clean bottom, remove mussels from prop, replace skeg zinc (70%) wasted

8/4/2025 Raw water, sink drain, head x 3 through hulls exercised. Manifold exercised.

10/5/2025 Raw water, sink drain, head x 3 through hulls exercised. Manifold exercised.